S-358
Bozman-Fitzgerald House
Venton vicinity
private

c. 1900

The Bozman-Fitzgerald house is a distinctive turn of the century farmhouse with its period Victorian trim. Common for the period is the two-and-a-half story three-bay elevation distinguished by a center cross gable. The pointed arch sash windows and the modest decorative Victorian trim are typical for these straightforward farmhouses. The detached kitchen served the house as the principal cooking area throughout the year.

Survey No. S-358

# Maryland Historical Trust State Historic Sites Inventory Form

Magi No. 2003585704

1. Nam	<b>1e</b> (indicate pr	eferred name)		
historic				
and/or common	Bozman - Fitzgeral	d House		
2. Loca				
street & number	r Fitzgerald Road			not for publication
city, town Ven	ton	X vicinity of	congressional district	First
state Maryla		county	Somerset	FIISC
	sification	County		
Category  district building(s) structure site _ object	Ownership public private both Public Acquisition in process being considerednot_applicable	Status  occupied unoccupied work in progress Accessible yes: restricted yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park priyate residence religious scientific transportation other:
4. Own	er of Prope	rty (give names a	nd mailing addresse	s of <u>all</u> owners)
name Robert	Fitzgerald			
street & number	"Waller's Adventur	e"	telephone no	).:
city, town Pri	ncess Anne	state	and zip code Maryl	and 21853
5. Loca	ation of Leg	al Description		
courthouse, regi	stry of deeds, etc. Som	erset Clerk of Cour	t	liber
street & number	Somerset County	Courthouse		folio
city, town Pri	ncess Anne		state M	Maryland 21853
6. Rep	resentation	in Existing	Historical Surve	eys
title				
date			federal state	e county loca
depository for su	rvey records			
city, town	77		state	

# 7. Description Survey No. S-358

Condition excellent good _X fair	deteriorated ruins unexposed	Check one unaltered _X_ altered	Check one _X_ original si moved	ite date of move	
_A_ tair	unexposed				

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

#### Bozman-Fitzgerald House Description

The Bozman-Fitzgerald house stands on the north side of Fitzgerald Road near Venton, Somerset County, Maryland. The two-story, center hall frame house faces south with the principal gable oriented on an east/west axis.

Built around 1900, the two-story weatherboarded frame house is supported by a new brick and concrete foundation, and is covered with asphalt shingles over wood shingles. Attached to the back of the house is a two-story wing, and an old detached kitchen is sited behind the house.

The south (main) elevation is a two-story, three-bay facade with a center entrance and flanking two-over-two sash windows. A shed roof porch distinguished with a center gable and decorative eave trim shelters the first floor openings. The turned porch posts have been removed temporarily while the porch floor is being rebuilt. A four-panel door with shallow raised panels remains in place. The second floor is lighted by three evenly spaced two-over-two sash windows, and the cross gable has a pointed arch two-over-two sash window. The eaves to the house are trimmed with decorative sawtooth edging, and the gable front is sheathed with fishscale shingles. Narrow brick stove stacks rise from the center of the house on either side of the passage.

The east and west gable ends are essentially alike with a single two-over-two sash window on each floor, and a pointed arch attic window is surrounded by a field of fish-scale shingles. Wooden finials rise from each roof peak.

The north side of the main block is largely covered by the two-story, one-room plan wing. A shed porch is fixed to the east side, and the porch has been partially enclosed to house a first floor bathroom. Two-over-two sash windows light the first and second floors, and a narrow brick stack rises from the gable end.

The interiors of the house retain large portions of the turn of the century wood-work; however, the center stair has been vandalized and the turned newel post, balusters and handrail have been removed. The stringer retains its Victorian decoration, and narrow beaded boards sheathe the triangular space below. Shallow four-panel doors are framed by molded surrounds with bulls-eye blocks. The west room retains its period mantel as well as paneled window aprons and simply molded baseboards. The turn of the century plaster remains intact as well. The east room is finished in a similar manner with a late Victorian mantel, plaster walls, and ogee molded baseboards.

The back room is fitted with narrow beaded board wainscoting, and a four-panel door opens into the space beneath the stair in the middle room. The small room behind the wainscoted room was used as a pantry. The second floor is finished in less elaborate manner with turn of the century woodwork.

Standing separately behind the house is the old detached kitchen, a single-story, one-room plan frame structure supported by a brick pier foundation and sheathed with asphalt shingles over weatherboards. A door is located in the south side, and single two-over-two sash windows light either side. A narrow stove stack formerly pierced the

<u>8. S</u>	ign	ificance		Survey No. S-358	
_ 1400 _ 1500	⊢1799 ⊢1899	archeology-historic agriculture X architecture art commerce		iterature military music philosophy politics/government	religion science sculpture social/ humanitarian theater transportation other (specify)
Specific	dates		Builder/Architect		· · · · · · · · · · · · · · · · · · ·
check:	aı App1:	cable Criteria: _And/or cable Exception:	A _B _C _D	_ <del>_</del>	
********	Leve.	of Significance:	_nationalstate	local	
Prepare support	both	a summary paragraph o	of significance and	a general statement of	f history and

## Significance

The Bozman-Fitzgerald house is a distinctive turn of the century farmhouse with its period Victorian trim. Common for the period is the two-and-a-half story three-bay elevation distinguished by a cross gable. The pointed arch attic windows and the modest decorative Victioran trim are typical for these straightforward farmhouses. The detached kitchen evidently served the house throughout the year.

## 9. Major Bibliographical References

Survey	No.	S-358
--------	-----	-------

10. Geographic	cai Data			
Acreage of nominated property Quadrangle name UTM References do NOT comp				Quadrangle scale
<b>^</b>	thing	B Zor	ne East	ing Northing
C		D	_     <u> </u> _   <u>   </u>	
Verbal boundary description a	nd justification			
List all states and counties fo	r properties over	lapping state o	r county	boundaries
List all states and counties fo	r properties over	county	r county	<b>boundaries</b> code
	-		r county	
state	code	county	or county	code
state	code code ared By	county	r county	code
state  11. Form Preparame/title Paul Touart - A	code code ared By	county  county  Historian	date	code
state  11. Form Preparame/title Paul Touart - Appropriation Somerset County	code code ared By	county  county  Historian		code code

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust


Shaw House 21 State Circle

Annapolis, Maryland 21401

(301) 269-2438

### Description cont.

north gable, but the stack has been leveled off at the roofline. The interior is sheathed with narrow beaded boards, and cabinets are fixed to the northwest corner of the room.





Bozman-Fitzgerald House Venton Vicinity, Somerset Co. Md. Mantel 6/86, Paul Touart, Photographer Neg/Md. Historical Trust

S-358



Bozman-Fitzgerald House S-358 Venton vicinity, Somerset County, Md. Interior window trim 6/86 Photographer - Paul Touart Neg/Md. Historical Trust



Venton vicinity, Somerset Co. Md. East Elevation 6/86, Paul Touart, Photographer

Bozman-Fitzgerald House

Neg/Md. Historical Trust

S-358



Bozman-Fitzgerald House S-358
Venton Vicinity, Somerset Co. Md.
South Elevation
6/86, Paul Touart, Photographer
Neg/Md. Historical Trust